

Failed restaurants

Burger King 1200 Bridge St

10-3-17 Fail ---- Hood out of date Schedule Cleaning PASS 10-12-17

Bani Restaurant 681 Merrimack St

10-4-17 Fail ----- Fire Extinguishers outdated have them inspected PASS 10-12-17

Domino's Pizza

10-4-17 Fail ----- Water Temp not getting higher than 84 degrees PASS 10-5-17

Have adjusted immediately

Lucky Market 4 Pine St

9-20-17 Fail --- clear walk-in freezer to many items, dumpster gone –replace,

Adjust temp on hot water only reaching 110 degrees

Sandwich King ---- 361 Bridge St

10-06-17 Fail --- clean Kitchen, clean and correctly organize al freezers and refrigerators, replace all missing and/or stained ceiling tiles, wash all walls, Exterminate mice roaches, have hood cleaned and dated, install paper towels in men's room, install thermometers in fridges, clear rear egress, have ansul system checked, clean meat slicer and dough mixer, repair and paint wall PASS 10-7-17